


# From the inquiry to the delivery of a DKD-calibration



**For brisk handling of a calibration order following devices and accessories are necessary:**

| Delivery of        |                           | Remark   |
|--------------------|---------------------------|--|
| 1. Sensor          |                           |  |
|                    | Data sheet of sensor      | not for Lorenz products                        |
|                    | Dimension sheet of sensor | not for Lorenz products                        |
|                    | Pin assignment of sensor  | not for Lorenz products                        |
| 2. Meas. amplifier |                           | if calibration of meas. Chain is intended      |
|                    | Operating instruction     | not for Lorenz products                        |
| 3. Meas. cable     |                           | if calibration is intended with provided cable |
| 4. Supply unit     |                           | if not integrated in the meas. amplifier       |
|                    | Operating instruction     | not for Lorenz products                        |

Equip all instruments and cables with ID-number.

**Packing of measuring instruments:**

Pack measuring instrument into a lockable plastic bag for protection from humidity

Pack measuring instrument into as sturdy box, which offers protection from impacts and humidity

Seal package well

pack measuring instruments individually (impact protection).